Cypress Sweeps Chimney Service 13525 Paseo Terrano Salinas, CA 93908 CA. Lic. 920383 (831) 642-0402

Customer JAMEJ	Frangella
Address 1840	870 ST
City <u>Seuside</u>	State CA Zip 93953
Phone (831) 521 -	2099
E-mail	
Date 6-3-14	Time
Directions to Home	

CONDITION REPORT	Satisfactory	Unsatisfactory	Not Applicable
CHIMNEY			
1. Height 42"	X		
2. Chimney Cap / Spark Arrestor	X		
3. Crown / Wash	X		
4. Brickwork / Mortar	X	-	
5. Flashing	X		
6. Flue Liner	X		
7. Moisture Resistance	X		
FIREPLACE SMOKE	/		
8. Smoke Chamber	X	- 3	
9. Damper OPM	X		
10 Firebox / Grate	, ,	X	
11. Ash Container			X
12. Spark Screen / Doors	X		
13. Tools / Gloves			X
14 Hearth Protection 7 13" 5 2 3	X	X	
15. Misc.:			
WOODSTOVE OR FIREPLACE INSERT			
16. Stovepipe Condition (woodstove)			X
17. NFPA Approved Flue Connection			X
18. Installation / Thimble / Clearances			X
OTHER SAFETY CONSIDERATIONS			
19. Fire Ext. / Smoke Detectors / CO Alarms			X
20. Gas / Oil Furnace Flue Liner			X
21. Fire Escape Plan			Y

Note: This sheet is the result of a visual inspection done at the time of cleaning. It is intended as a convenience to our customer, not as certification of fire worthiness or safety. Since conditions of use and hidden construction defects are beyond our control, we make no warranty of the safety or function of any appliance and none is to be implied.

14-270 2	482699
 Type of Fireplace: Prefab Masonry No. of Stories: 3 4 No. of Fireple Woodstove: Insert Freestanding Type of Wood Used: Soft Hard Soft New Last Cleaned: Year(s) Ago New Number of cords burned per season: New 	☐ Pellet/Corn] Wet ☐ Dry
 Flue Size: 8" × 8" 8" × 13" 13" 13" × 13" 13" 13" × 13" 13"	× "" adio
COMMENTS:	
10) Cracked bricks rear u	right of
the proper hearth prote	16 Kingue
CUSTOMER VERIFICATION I have read this form and now understand wh chimney system appear to be satisfactory and not satisfactory. Signed	which areas are
I have read this form and now understand wh chimney system appear to be satisfactory and not satisfactory. Signed Da	which areas are
I have read this form and now understand wh chimney system appear to be satisfactory and not satisfactory. Signed	which areas are
I have read this form and now understand wh chimney system appear to be satisfactory and not satisfactory. Signed Da	teattime
I have read this form and now understand wh chimney system appear to be satisfactory and not satisfactory. Signed	teattime
I have read this form and now understand who chimney system appear to be satisfactory and not satisfactory. Signed	teattime
I have read this form and now understand whe chimney system appear to be satisfactory and not satisfactory. Signed	attime ard states the fire- for any structural
I have read this form and now understand whe chimney system appear to be satisfactory and not satisfactory. Signed	attime ard states the fire- for any structural
I have read this form and now understand whe chimney system appear to be satisfactory and not satisfactory. Signed	attime ard states the fire- for any structural
I have read this form and now understand whe chimney system appear to be satisfactory and not satisfactory. Signed	attime ard states the fire- for any structural PRICE 1/5
I have read this form and now understand whe chimney system appear to be satisfactory and not satisfactory. Signed	attime ard states the fire- for any structural PRICE 145 AL